







Power Supply
115VAC/60Hz/18A







Clamp Meter Switch Manual/Auto LED White Power on LED Green Machine Running LED Yellow Filter Warning Motor Relay Hour counter

/2.2 13 14
/3.7 23 24







-10K2

16Input DC24V				16Output DC24V				8Universal Analog Input/ 8Analog output 0-10V				8 Counter Input			
X10;1	I0.0	/7.1	Switch Manual=1	-X12;1	Q0.0	/8.2	LED Running	-X14;1	I2.0	-X15;1	I3.0	-X15;1	I3.0		
X10;2	I0.1	/7.7	Clamp Meter	-X12;2	Q0.1	/8.3	LED Filter Warning	-X14;2	I2.1	-X15;2	I3.1	-X15;2	I3.1		
X10;3	I0.2			-X12;3	Q0.2			-X14;3	I2.2	-X15;3	I3.2	-X15;3	I3.2		
X10;4	I0.3			-X12;4	Q0.3			-X14;4	I2.3	-X15;4	I3.3	-X15;4	I3.3		
X10;5	I0.4			-X12;5	Q0.4			-X14;5	I2.4	-X15;5	I3.4	-X15;5	I3.4		
X10;6	I0.5			-X12;6	Q0.5			-X14;6	I2.5	-X15;6	I3.5	-X15;6	I3.5		
X10;7	I0.6			-X12;7	Q0.6			-X14;7	I2.6	-X15;7	I3.6	-X15;7	I3.6		
X10;8	I0.7			-X12;8	Q0.7			-X14;8	I2.7	-X15;8	I3.7	-X15;8	I3.7		
X11;1	I1.0	/7.3	PA Switch	-X13;1	Q1.0	/8.4	Motor Relay	-X16;1	Q2.0						
X11;2	I1.1			-X13;2	Q1.1			-X16;2	Q2.1						
X11;3	I1.2			-X13;3	Q1.2	/8.6	Valve 1 Cleaning	-X16;3	Q2.2						
X11;4	I1.3			-X13;4	Q1.3	/8.7	Valve 2 Cleaning	-X16;4	Q2.3						
X11;5	I1.4			-X13;5	Q1.4			-X16;5	Q2.4						
X11;6	I1.5			-X13;6	Q1.5			-X16;6	Q2.5						
X11;7	I1.6			-X13;7	Q1.6			-X16;7	Q2.6						
X11;8	I1.7			-X13;8	Q1.7			-X16;8	Q2.7						

/4.8 >CLM

046
1/18 BU/WH

/4.8 >PA

050
0,5/20 BU

/4.8 >MANUAL

041
0,5/20 BU

X10;1

X11;1

.....	
I0.0	I1.0
Switch Manual=1 Auto=0	PA Switch
Digital input	Digital input

/6.0

-10K2

-10K2

Relay Clamp Meter

/7.7 13 14

+24VDC /5.8

24V
1/18 BU

-11K5
/7.5

064
0,5/20 BU

X10;2

.....
IO.1
Clamp Meter
Digital input

/6.0

-10K2

